



Case Study


Storm Damage to Fencing and Shed in South East London

Presented by: Matt Reed

Client Name
Insurance Sector

Project Details
Property Type: Four-bedroom residential property with rear garden

Before Photos



After Photos



Project Overview

Following a storm which led to a tree falling onto three fence panels and an adjacent shed, these three fence panels were reinstated, alongside the four fence posts in between. This required careful planning, due to external factors, including neighbouring roots and nearby shed foundations. Discretion and speediness were of the utmost importance due to neighbour's boundaries being exposed.

Works Undertaken

- Removal and clearance of existing fence panels
- Careful excavation of the ground
- Fence panel and post installation
- Specialist timber treatment

Project Specifications

- Contract Period: 2 days
- Project Value: £3.5k